

EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies. **810609**

MI #198

MIS-000-001-017

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name BASF Wyandotte Corporation
Street P. O. Box 181
City Parsippany, State N.J. Zip Code 07054

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site BASF Wyandotte Corp. - North Works
Street 1609 Biddle Avenue
City Wyandotte County Wayne State MI Zip Code 48192

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Gebrian, J., Manager Corporate Environmental Protection
Phone (201) 263-5674

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1895 To (Year) Present 1981

E Waste Type:

- 1) Landfill -- A landfill, not presently used, exists within the plant boundary line. The landfill has received the following hazardous wastes;
 - a) Filter cake - ignitable (D001)
- 2) In August 1975, a spill of 15,000 gallons of styrene, an ignitable material (D001) occurred. Michigan DNR suggestions for recovery were followed.
- 3) Large quantities of dichloropropane (U077) and dichloroethane (K019) are stored in a salt cavern beneath the property.
- 4) In the past, unknown quantities of hazardous wastes, were stored on the site (mostly in drums) before disposal to outside facilities.
- 5) Coke Plant - In the past, BASF operated a Coke plant in the North Works. Spills of ammonia still lime sludge (K060) and Decanter tank tar sludge (K067) could have occurred to the ground.

US EPA RECORDS CENTER REGION 5



406749

000478 JUN -981

JUN 12 1981

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☒ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet _____

gallons _____

Total Facility Area

square feet _____

acres 230**G Known, Suspected or Likely Releases to the Environment:**

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ NoneUnknown

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person providing notification. If you are not required

Name Dunn, R. E., Secretary of
BASF Wyandotte Corporation

Street P.O. Box 181

City Parsippany State N.J. Zip code 07054

Signature R. E. Dunn

Date 6/5/84

- ☒ Owner, Present
☐ Owner, Past
☐ Transporter
☒ Operator, Present
☐ Operator, Past
☐ Other

BASF Wyandotte Corporation

BASF



100 Cherry Hill Road
P.O. Box 181
Larsippany, N.J. 07054
201/283-0200

Certified Mail
P29 2144633

June 5, 1981

U. S. EPA Region 5
Sites Notification
Chicago, Ill 60604

Gentlemen:

Enclosed are the submissions of hazardous waste sites as required by Section 103(c) of the Comprehensive Environmental Response, Compensation and Liability Act of 1980.

BASF Wyandotte Corporation owns and operates the following;

Holland, Michigan
Wyandotte, Michigan

BASF Wyandotte Corporation formerly owned and operated the following;

Riverview, Michigan
Port Edwards, Wisconsin

Very truly yours,

Keith Fry
Keith Fry, Director
Corporate Environmental
Protection

KF:if
enclosures

JUN 12 1981



BASF Wyandotte Corporation
100 Cherry Hill Road
P.O. Box 181
Parsippany, N.J. 07054

US EPA Region 5
Sites Notification
Chicago, ILL 60604

RETURN RECEIPT
REQUESTED



CERTIFIED
MAIL
P29 2144633